


THERMISTOR BEAD IN TIP

LEAD WIRE, MANAGE EXCESS CORD LENGTH IN NEAT BUNDLES NEAR CONTACT.

TEMPERATURE PROBE

MOUNT TEMP SENSOR TO HORIZONTAL SIDE OF PIPE, NOT TOP OR BOTTOM. STRAP SENSOR TIGHT TO PIPE WALL. DO NOT "CINCH" INSULATION.



HIGH OR LOW TEMPERATURE PIPE SENSOR WITH INSULATION

RMCS TEMPERATURE SENSORS

NO SCALE

DATE JUN 2022	DEFENSE COMMISSARY AGENCY DIRECTORATE OF ENGINEERING FORT LEE, VIRGINIA - LACKLAND AFB, TEXAS	DESIGN STANDARD 230916-11
		TITLE TYPICAL RMCS TEMPERATURE SENSORS